

FIG 1d




FIG 1c




FIG 1b




FIG 1a




FIG 2d




FIG 2c




FIG 2b





FIG 2a



A schematic diagram of a mechanical assembly. A horizontal shaft passes through a central block. On the left side of the shaft, there is a pin or bolt passing through a flange. A spring is attached to the right end of the shaft. The spring is connected to a vertical plate. The vertical plate has two rectangular blocks attached to it, one above and one below the shaft. The entire assembly is supported by a base structure.

FIG 4d




FIG 4c




FIG 4b




FIG 4a

